

CLIENT INFORMATION

Name:	Lansingburgh Central School District
Address:	576 Fifth Ave Troy Ny 12182
Client Rep:	Bob Schongar

Date of Sampling:	4/22/21	5/15/2021	7/9/2021
Samples Taken By:	Tim LeVan	Jack Thomas	Ken Retell
Samples Taken By:	Jack Thomas	Ken Retell	Jack Thomas

SCHOOL/PROJECT INFORMATION

BLDG NO./NAME:	Knickerbacker middle school
BLDG ADDRESS:	320 Seventh Ave Troy NY 12182
CONTACT NAME & NUMBERS:	Bob Schongar 518-858-5580

(1) Yr. Built	(2) Yr 1st Add:	(3) Yr 2nd Add:	(4) Yr 1st Mod:	(5) Yr. 2nd Mod:

SAMPLE DATA

Sample Description ID (ID must match container label)				Outlet Information							
Lab Sample #	BOCES Sample #	Location	Outlet Description	Outlet Make & Model	Construct. Date	First Draw	Time of Collection (24hr)	Lead test Results ug/L from 4/22/2021	Lead test Results ug/L from 5/15/21	Lead test Results ug/L from 7/9/2021	Remediation
52	KMS-02-BF-P-52	Rm 230 bathroom	Sink faucet			X	6:07	8.2			
53	KMS-02-BF-P-53	Rm 236 bathroom	Sink faucet			X	6:08	14.8			
54	KMS-03-CF1-P-54	Rm 334	Sink faucet	Chicago		X	6:12	26.2	17.7	35.9	Turned off for repair
55	KMS-03-CF2-P-55	Rm 332	Sink faucet	Royal		X	6:14	167	28.2	42.8	Turned off for repair
56	KMS-03-DW-P-56	3 RD floor corridor outside girls room	Water fountain	Elkay		X	6:16	5.9			
57	KMS-03-BF1-P-57	3 rd floor girls room	Sink faucet #1	Chicago		X	6:17	20.3	15.3	18	Turned off for repair
58	KMS-03-BF2-P-58	3 rd floor girls room	Sink faucet #2	Chicago		X	6:17	20.5	15.6	22.4	Turned off for repair
59	KMS-03-BF3-P-59	3 rd floor girls room	Sink faucet #3	Chicago		X	6:18	21.3	21.1	36.1	Turned off for repair
60	KMS-03-DW-P-60	3 RD floor corridor outside boys room	Water fountain	Elkay		X	6:19	<1.0			
61	KMS-03-DW-P-61	3 RD floor corridor outside boys room	Bottle filler	Elkay		X	6:19	<1.0			
62	KMS-03-BF1-P-62	3 RD floor boys room	Sink faucet #1	Chicago		X	6:20	11.8			
63	KMS-03-BF2-P-63	3 RD floor boys room	Sink faucet #2	Chicago		X	6:20	11.9			
64	KMS-03-DW-P-64	Cafeteria	Water fountain	Halsey Taylor		X	6:22	<1.0			
65	KMS-03-CF-P-65	Rm 317A	Sink faucet #1			X	6:21	12.0			
66	KMS-03-CF-P-66	Rm 317A	Sink faucet #2			X	6:23	17.5	36.8	67.5	Turned off for repair
67	KMS-03-CF1-P-67	Rm 317A	Sink faucet #3			X	6:23	14.0			
68	KMS-03-CF2-P-68	Rm 317A	Sink faucet #4			X	6:24	22.0	197	93.9	Turned off for repair
69	KMS-03-DW-P-69	3 rd floor corridor outside 312	Water fountain	Elkay		X	6:25	6.1			
70	KMS-03-CF-P-70	311	Sink faucet	Central		X	6:26	9.7			
71	KMS-03-BF-P-71	311B	Sink faucet			X	6:27	13.7			
72	KMS-03-CF-P-72	310	Sink faucet	Standard		X	6:27	35.4	26.9	25.8	Turned off for repair
73	KMS-03-CF-P-73	310	Sink faucet	Standard		X	6:27	23.6	21	21.3	Turned off for repair
74	KMS-03-BF-P-74	310A	Sink faucet	Standard		X	Not working No Sample				Removed

All containers are pre-cleaned/pre-certified 250ml plastic bottles and will be preserved w/HNO3@ pH by lab

CHAIN OF CUSTODY

Relinquished By:	Received By:	Time:	Date:

INSTRUCTIONS TO THE LABORATORY - Analyze all samples for lead (Pb)

Lab:	PACE Analytical
Contact:	
Comments:	Provide Laboratory Data Report (LDR) and Chain of Custody